

Product Safety Recall

SHAMROCK GIFT COMPANY RECALLS GUINNESS EMBOSSED MUGS

| Code | 02598 | 02597 | 02061 | 02748 |
|-------------|---|---|--|---|
| Barcode | 5390711031734 | 5390711031727 | 5390711025320 | 5390711602569 |
| Order No | 509201 / 508747 | 509012 | 508747 | 509012 |
| Description | Guinness Toucan Embossed Mug - Black | Guinness Label Embossed Mug | Guinness Toucan Embossed Mug - Red | Guinness Storehouse Embossed Mug |
| Image |  |  |  |  |

HAZARD

- Mugs purchased since May 2024 are at risk of Thermal Shock when hot water is added, which may cause a crack in the base of the Mug. In some cases, the base may detach causing a risk of injury and scalding.

WHAT TO DO

- Consumers should discontinue use of mug immediately
- Please return product to point of sale to receive full refund. Alternatively if this is not possible please contact customerservice@shamrockgiftcompany.com

REMEDY

- A full refund will be made available

CONTACT

- For further queries please email customerservice@shamrockgiftcompany.com

Guinness Embossed Mugs are produced under license by Shamrock Gift Company. Shamrock Gift Company sincerely apologise for the inconvenience caused by this recall.